



FIGURE 37 DETAILS OF BRICK VENEER AT GROUND AND FLOOR LEVELS (UNINSULATED CAVITY)